

RUST-OLEUM®

SPECIALTY

High Heat *Ultra*

Longest Lasting Finish

**Extra Rich Color
Semi-Gloss Sheen**

**Resists Heat
Up To 1200°**

**STOPS
RUST**

NET WT.

NET WT. 12 OZ. 340g*

PELIGRO! EXTREMADAMENTE INFLAMABLES. VAPORES INOCIVOS
PUEDEN CAUSAR UN INCENDIO REPENTINO. NO SOMETER A PRESION.
07 240-* Observar otras precauciones al verso.

Observar otros procedimientos al dorso

HIGH HEAT ULTRA is a superior rust-preventive enamel that provides deep color, rich sheen and the best protection for high heat surfaces. This durable semi-gloss finish gives metal surfaces a premium look along with excellent gloss and color retention after repeated heating. It withstands temperatures of up to 1200°F (648° C). Ideal for the outside of barbecue grills, wood stoves, radiators, fire pits, fireplace screens, automotive parts and more.

Painting Conditions: Use outdoors or in a well-ventilated area, such as an open garage. Use when temperature is between 50°F (10°C) and 90°F (32°C) and humidity is below 85% to ensure proper drying. Priming is not recommended. Do not use on metal directly exposed to flames or in direct contact with food, such as a grill grate. Avoid spraying in very windy, dusty conditions. Cover surrounding area to protect from overspray.

Preparation: Remove loose paint and rust with wire brush or sandpaper. Lightly sand glossy surfaces. Clean with soap and water, rinse and let dry.

Painting: Shake can vigorously for one minute after riding ball begins to rattle. Shake often during use. Hold can upright 12-16" from surface and spray in a steady back-and-forth motion, slightly overlapping each stroke. Keep the can the same distance from the surface. Keep the can in motion while spraying. Apply 2 or more light coats a few minutes apart.

Dry & Recoat Times based on 70°F–80% relative humidity. Allow more time at cooler temperatures. May recoat within 1 hour or after 48 hours. Allow paint to dry 1 hour before handling. It may emit smoke and harmless odor at first. Dries to the touch in 1/2 hour and is handle in 1–2 hours.

Clean-up: When finished spraying, close spray valve by turning can upside down and pushing spray button for 5 seconds. Clean up wet point with Xylene or mineral spirits. **Thawing:** Allow empty can to thaw in warm place. Do not burn or place in house trash container.

Chipping: If valve chips, twist and pull off spray tip and draw it in a solvent such as mineral spirits. Do not stick pin or other object into the stove.

CONTAINS: TOLUENE AND XYLENE. Vapor harmful. May affect the brain or nervous system causing dizziness, headache or nausea. Causes eye, skin, nose and throat irritation. Do not puncture, drill, or incandesce (burn) containers. Exposure to heat or prolonged exposure to sun may cause burning. Do not expose to heat or store at temperatures above 120°F (49°C). **HAZARD:** Vapors have caused repeated and prolonged occupational exposures to animals with permanent brain and nervous system damage. Inhalation causes by irritating concentrations irritating the content may be harmful or fatal. Vapors may flammable. Keep away from heat, sparks and flame. Do not smoke. Extinguish all flames and pilot lights and have all stoves, heaters, electric motors and other sources of ignition during use and out of use are present. Prevent build-up of vapors by opening all windows and doors to achieve cross-ventilation. Use only with adequate ventilation. Do not breathe that vapors or spray mist. Flush face if spray during application and dry eye. If you experience eye watering, irritation or discharge, wear emergency eyewash (MUST carry) or have the eye. Avoid contact with skin. Wash thoroughly after use. Do not use if you are pregnant or nursing.

comes from eyes, skin, clothing, etc. If you experience irritation or stinging, stop use to obtain fresh air. If irritation is experienced, get medical attention immediately. In case of eye contact, flush immediately with plenty of water for at least 15 minutes and get medical attention; for skin, wash thoroughly with soap and water. **WARNING:** This product contains a chemical known in the state of California to cause birth defects or other reproductive harm. **KEEP OUT OF REACH OF CHILDREN.** For emergency, call poison help, health professionals, contact your oral or dental emergency room. For product health information, call 800-451-4561.

SATISFACTION GUARANTEED: If you are dissatisfied with this product, contact our Customer Service Department for a full refund of the purchase price. Refer to product number and batch code on bottom of can.

SATISFACCIÓN GARANTIZADA: Si no está satisfecho(a) con este producto, haga favor de ponerse en contacto con nuestro Departamento de Atención al Cliente para el reembolso completo del precio de compra. Pedirán el número del producto y el código de lote en la parte inferior de la lata.

ULTRA ACTO CALOR es un escudo superior para la prevención de la colisión y también provee un mejor protección en accidentes de tránsito y la mayor protección para las superficies expuestas a un alto calor. Puede soportar altas temperaturas de hasta 945 °C (1745 °F). Es ideal para las extremidades de pernos para buques, cables para la industria, soldaduras, chimeneas, puentes para chimeneas, partes y accesorios de autoservicio y muchos otros artículos expuestos al calor.

Una cosa con la que se puede jugar es en el exterior o en un área bien ventilada como un patio o jardín. **Siendo** la temperatura se encuentre sobre 50°C (120°F) y la humedad debajo de un 60%, puede asegurarse un suceso exitoso. No se recomienda la utilización de una primera capa para la preparación de la superficie. No use un suelo que esté directamente adyacente a las líneas del edificio o que esté en contacto directo con las alcantarillas, como en el caso de la sala de un puerto. Esto le explicación usando recubrimiento cuando condiciones con mucha viento o nieve. Cuando el área circundante para protegerla contra la lluvia del rodado. **Preparación:** Ponerse la primera capa y/o los otros cubriendo un cubo de plástico o papel. En la siguiente las superficies rodeadas. Limpiar con jabón y agua, manguera y dote seca. Agregar la lata suavemente por un rodado después de haber sacado el exceso de la lata. **Resistencia:** Agregar la segunda capa de 100 g. La lata debería cubrirse a 12-15 pulgadas desde la superficie y/o en un momento de trabajo para cada capa, asegurando que cada nueva pintura cubra las anteriores. Mantenga la lata a la misma distancia desde la superficie. Mantenga la lata en movimiento durante todo el rodado. Aplique dos o tres capas después que se sienta cómodo sobre **Temperatura de Secado y una Aplicación de Otro Capa** una temperatura de 23°C y una humedad relativa de un 50%. Permita más tiempo en temperaturas más altas. Se puede aplicar otra capa dentro de un día y después de 48 horas. Permita que la pintura seque por 12 horas antes de conducir. Al principio puede sentir horma y olor indeseados. Si, al hecho en un 12 horas y/o un punto seguir en 1-2 horas. **Limpiar:** Al terminar de rodar, limpiar las vueltas mediante la lata de la parte más lejos y después de cada por 5 segundos. Limpieza de la pintura mediante con agua y cepillos suaves. Lavarla la lata veces en el lavadero. No queme o ponga en un compactor/domicilio para quemar. **Precauciones:** Si la vitrola no funciona, lavar girar y/o el exterior (dentro para recubrir) y/o después con un solvente como acetona de rodado. No incinerar ni usar o quemar otro tipo de combustible para la rodado.

Abstract

[illegible]

RUST-OLEUM®
CORPORATION
11 Hawthorn Pkwy., Vernon Hills, IL 60061
rustoleum.com

©2006 Rust-Oleum Corporation. Made in USA. Hachem E.L.A. 241961 1002

Ball
An RPM Company
paintideas.com
1-800-481-4785
DOT 2P M5702